



# 2017 Emergency Repair Program PHOTO SUBMITTAL EXAMPLE



Good overall road perspective view

Pavement distress clearly visible with minimal disruption from shadows or other factors

Pavement marked for clear definition of repair

Repair area marked with identifying mark

Shrink photo to be 1600x1200 or smaller

Submit in a .jpg, .png, or .pdf format



# 2017 Emergency Repair Program

## EXAMPLES OF ACCEPTABLE REPAIRS

- GOOD BASE
- ISOLATED REPAIRS
- 2016-2017 WINTER DAMAGE



-Good Base

-Isolated Repair



-Good Base

-Isolated Repair



# 2017 Emergency Repair Program

## EXAMPLES OF ACCEPTABLE REPAIRS



- Good Base
- Isolated Repair



- Good Base
- Narrow Strip Repair



# 2017 Emergency Repair Program

## EXAMPLES OF NON-ACCEPTABLE REPAIR

- Greater than 25% distressed
- Insufficient base
- Patching is insufficient treatment
- History of failure



-Greater than 25% distressed

-Correct treatment is reconstruction



-History of failure

-Greater than 25% distressed



# 2017 Emergency Repair Program

## EXAMPLES OF NON-ACCEPTABLE REPAIR



-The correct treatment requires more than patching

-Greater than 25% distressed



-No Base



# 2017 Emergency Repair Program EXAMPLES OF NON-ACCEPTABLE REPAIRS



-Bad workmanship

-Pavement in too good of condition to be considered "emergency"





## 2017 Emergency Repair Program **EXAMPLES OF NON-ACCEPTABLE REPAIRS**



- The correct treatment requires more than patching

-Greater than 25% distressed



# 2017 Emergency Repair Program

## EXAMPLE OF COMPLETED PATCH REPAIR

Non-distressed  
adjoining pavement

Sawcut or grind  
vertical edges



Smooth compacted  
asphalt surface

Sealed edges